

S No.	Questions	Answer	Comments

4. Ad Hoc Deficiency

S No.	Deficiency
1	On the playground, there is an uncovered pipe in the ground.
2	There is an exposed nail on the fence located on the right side of the playground.
3	There are multiple broken boards along the backside of the fence.



Provider's Signature